
WIDE ANGLE ARROWHEAD

PARTS LIST

| 10 | wide angle arrowhead | 40 | ferrule |
|-------|--------------------------|-------|---------------------|
| 10a-b | wide angle arrowheads | 42 | arrow shaft |
| 12 | mounting fixture | 44 | interior bevel |
| 14 | chisel point | 46 | interior wide angle |
| | - | 48 | centerline |
| 16 | circular recess | 50 | narrow angle blade |
| 18 | first shaft portion | 52 | chisel point |
| 20 | beveled ring | 54 | interior wide angle |
| 22 | second shaft portion | 56a-b | blades |
| | | 58 | wide angle |
| 24a-n | slots | 60a-b | blades |
| 26 | threaded shaft portion | 62 | interior wide angle |
| 28a-n | blades | | · |
| 30 | blade base edge | | |
| 32 | blade cutting edge | | • |
| 34 | blade trailing edge | | |
| 36 | blade capture protrusion | | |
| 38 | blade capture point | | |






FIG. 2

